



BMW 3 BERLINE: 1KRD767			
Vinnnumber:	WBA3W31030K315954	Versionname:	2.0 316D (85KW) BERLINE
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	194539	Power Kw:	85
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2410
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	1135,72
Front bumper, Damaged, Le - Replace and paint	735,00



Windscreen, Bad repair, P - Check	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Bumper grille F R, Accident, P - Check 0,00

No pictures to display

Door panel R R, Damaged, Smart repair 110,64



Foglight R, Accident, P - Check 0,00

No pictures to display