



BMW 316D: 1GCY886

Vinnumber:	WBA3D91000J413287	Versionname:	DIESEL
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	149132	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	23000KM	Parking lot:	1333
Maintenance:	01-01-20		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 5 mm	Re.R.	BF Goodrich: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	575,75
-------------------	---------------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------



Door F R, Bump(s), Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00



Door panel R R, Tear, E - Replace 114,00



Door panel F R, Tear, E - Replace 114,00



Door panel R L, Tear, E - Replace 114,00



Wing F L, Bump(s), PDR - Knock out without painting 63,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00



Wing R L, Scratch(es), 67 - Polish 55,19



Door R R, Bump(s), Acceptable 0,00



Seat cover F L, Worn, Acceptable 0,00



Sill trim R, Scratch(es), It - Spot repair 115,56



Bumper R, Scratch(es), Acceptable 0,00

