




AUDI A4 AVANT: 1KAP973				
Vinnnumber:	WAUZZZ8K6FA107240	Versionname:	2.0 TDI 110KW MULTITRONIC	
First Registrationdate:	19/03/2015	Fiscalpower:		
Expertise Mileage:	79695	Power Kw:	110	
Bodytype:	Break	Body color	Dark Blue	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3331	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar	Tow bar fixed	
Steering wheel multifunctional				
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Winter tyres:	225/55/16/92 H LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Total cost ex VAT			1090,41	
Wing R R, Bad repair, Paint			0,00	
				
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08	



Boot carpet, Dirty, Cleaning	50,00
------------------------------	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------




Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display