



BMW 5: 1GKT020			
Vinnnumber:	WBA5J110X0D065547	Versionname:	5 TOURING 518dA 136PK Aut.
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	67941	Power Kw:	100
Bodytype:	Break	Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1528
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	245/45/18/96 V LightMetal			
	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment		
	Runflat	Yes
Total cost ex VAT		95,00
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00





Door F R, Bump(s), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	