



JAGUAR XF: KG9678			
Vinnumber:	SAJAA05K0EDU22895	Versionname:	2.2D 147KW AUTO R-SPORT INTERIOR
First Registrationdate:	15/01/2016	Fiscalpower:	
Expertise Mileage:	82246	Power Kw:	147
Bodytype:		Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1431
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	245/45/18/100 V LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
			Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.
			Michelin: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			4426,83
Bonnet, Chemical polution, LI - Repair and paint (complete)			348,09



Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------




Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------

Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Damaged, E - Replace 560,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02




Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

254,16

