



HYUNDAI ix35: 1GPU470			
Vinnnumber:	TMAJU81VCEJ570724	Versionname:	ix35 4WD Executive
First Registrationdate:	27/03/2014	Fiscalpower:	136PK
Expertise Mileage:	121888	Power Kw:	100
Bodytype:	SUV	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2428
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/55/18/96 H LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			375,18
Wing R L, Bump(s), Acceptable			0,00
No pictures to display			
Mirror side blinker L, Broken, E - Replace			30,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
--	--	--	-------



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Mirror side blinker R, Broken, E - Replace	30,00
--	-------



Ceiling, Worn, Acceptable	0,00
---------------------------	------

