



BMW 5: HC1871			
Vinnnumber:	WBA5K31060D924495	Versionname:	5 TOURING 530dXA 258PK Aut.
First Registrationdate:	18/09/2014	Fiscalpower:	
Expertise Mileage:	118841	Power Kw:	190
Bodytype:	Break	Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2404
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

||
||
||



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Interior, Dirty, Cleaning	100,00
---------------------------	--------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------

