


FORD Galaxy: 1FBP129

Vinnnumber:	WF0MXXGBWMDP24911	Versionname:	GALAXY Ghia DPF 136PK
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	199623	Power Kw:	100
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3819
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare wheel	No	Compressor	No
Emergency spare wheel	No	Jack	No
Repair kit	No	Runflat	No

Total cost ex VAT	1680,66
-------------------	----------------

Gear shift lever cover, Worn, Acceptable	0,00
--	-------------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	-------------

 		Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
  		Door F R, Bad repair, Paint	0,00
 		Wing R L, Bump(s), PDR - Knock out without painting	159,00
 		Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
 		Door R R, Bad repair, Paint	0,00
  		Wing F R, Scratch(es), Acceptable	0,00
No pictures to display		Windscreen, Stone chip(s), Acceptable	0,00
No pictures to display		Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
 		Wing R R, Bump(s), LI - Repair and paint (complete)	417,84
  		Ceiling, Stain, Cleaning	25,00
  		Tyre repair kit, Missing, E - Replace	252,64
No pictures to display		Door R L, Scratch(es), LI - Repair and paint (complete)	382,02

