



CITROEN C4: 1ERK422			
Vinnnumber:	VF7NC9HP0CY638904	Versionname:	C4 BER Business GPS FAP 92PK
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	118327	Power Kw:	68
Bodytype:	Hatchback	Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4224
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		






Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear			
Summer tyres:	205/55/16/91 V LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
			Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.
			Michelin: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2637,76
Rearview mirror housing L, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Scratch(es), It - Spot repair			115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

  			
			
Roof, Chemical polution, LI - Repair and paint (complete)			481,50
  			
Tailgate, Scratch(es), LI - Repair and paint (complete)			301,68
  			
 			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
  			
			
Door R R, Scratch(es), Acceptable			0,00
No pictures to display			
Wing F R, Chemical polution, LI - Repair and paint (complete)			220,18
  			
Door F R, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00
  			
Rear spoiler, Chemical polution, LI - Repair and paint (complete)			115,56
 			
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Roof pillar L, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Wing R R, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display