




CITRO?N C4 Picasso: 1GIL295			
Vinnnumber:	VF73A9HP8EJ552950	Versionname:	GR.C4 PICASSO Business
First Registrationdate:	17/02/2014	Fiscalpower:	GPS ETG 92PK Aut.
Expertise Mileage:	148769	Power Kw:	68
Bodytype:	MPV	Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4228
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
	205/60/16/92 H LightMetal		
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.
	Re.L.	Goodyear: 4 mm	Re.R.

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1918,61
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

 		Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
   		Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
      		Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
 		Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display		Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
 		Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
 		Door R R, Scratch(es), Acceptable	0,00
No pictures to display		Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
  		Interior, Dirty, Cleaning	50,00

