




BMW X1: 1GKS031			
Vinnnumber:	WBAVY11010VZ66425	Versionname:	X1 sDrive16 116PK Aut.
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	82949	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1207
Maintenance	IN 6000 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Winter tyres:	225/45/18/91 H LightMetal		
	Fr.L.	Pirelli: 6 mm	Fr.R.
			Pirelli: 6 mm
	Re.L.	Pirelli: 4 mm	Re.R.
			Pirelli: 4 mm
Assistance equipment			
	Runflat		Yes
Total cost ex VAT			2158,87
Rearview mirror housing L, Broken, E - Replace			138,99
 			
Roof pillar L, Scratch(es), It - Spot repair			115,56




Spoiler R, Scratch(es), It - Spot repair

115,56



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Interior, Dirty, Cleaning

50,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)

290,08

