



BMW X4: HL8505			
Vinnnumber:	WBAXX110400R37378	Versionname:	2.0 XDRIVE20D (140KW)
First Registrationdate:	21/10/2015	Fiscalpower:	4WD
Expertise Mileage:	33224	Power Kw:	140
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2611
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		


Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/60/17/99 H LightMetal			
	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	1906,58
Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09





Door F R, Bump(s), Acceptable 0,00

No pictures to display


Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Brand badge R, Strained , E - Replace 54,89



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02




Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84





Wing R R, Stone chip(s), Acceptable	0,00
No pictures to display	
Central pillar L, Scratch(es), It - Spot repair	115,56

