



BMW 5: SM8957

Vinnnumber:	WBA5J51060D580567	Versionname:	5 TOURING 520dXA 184PK Aut.
First Registrationdate:	4/03/2014	Fiscalpower:	
Expertise Mileage:	110735	Power Kw:	135
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2116
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Total cost ex VAT:	469,16		
Door R R, Bad repair, Paint:	0,00		



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear wiper arm, Incomplete, E - Replace	25,00
---	-------



Door F R, Bad repair, Paint	0,00
-----------------------------	------

