



MERCEDES A 200 CDI: 1HCD927

Vinnumber:	WDD1760081V020310	Versionname:	A 200 CDI 136PK
First Registrationdate:	17/06/2014	Fiscalpower:	
Expertise Mileage:	95219	Power Kw:	100
Bodytype:		Body color	Light Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	19/03/2018	Parking lot	1230
Maintenance	OK		
Maintenance	B IN 68 DAYS		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	1		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Manual climate control
Level control	
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	1685,14
-------------------	---------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), E - Replace

487,20



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), E - Replace

174,16



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80

