



MINI Clubman: 1BXR706			
Vinnnumber:	WMWZH51060TX91464	Versionname:	MINI CLUBMAN Cooper D 112PK DPF
First Registrationdate:	29/09/2011	Fiscalpower:	
Expertise Mileage:	80860	Power Kw:	82
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Body color	GRIS BRUN
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	1307
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	205/45/17/84 V LightMetal		
	Fr.L.	Dunlop: 4 mm	Fr.R.
			Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.
			Dunlop: 5 mm

Assistance equipment	
Jack	Yes
Runflat	Yes

Total cost ex VAT	930,71
Floor covering F L, Worn, Acceptable	0,00

No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Repaired, Acceptable	0,00
------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------

