


SKODA SUPERB COMBI: 1JXJ948

Vinnnumber:	TMBJE73T3F9044115	Versionname:	2.0 CRTDI 103KW ELEGANCE
First Registrationdate:	12/03/2015	Fiscalpower:	
Expertise Mileage:	158637	Power Kw:	103
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1527
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Central consol F	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting Xenon	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining semi-artificial leather	Type of Tow bar	Tow bar fixed
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 H LightMetal			
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1544,94
-------------------	---------

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Bumper R, Damaged, Le - Replace and paint	0,00
---	------



Tailgate, Damaged, Le - Replace and paint	1034,68
---	---------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	0,00
--	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	0,00
--	------



Rearlight R , Damaged, E - Replace	0,00
------------------------------------	------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display