


**RENAULT Grand Espace: 1FH792**

Vinnumber:	<b>VF1JKFJC649299561</b>	Versionname:	<b>GR.ESPACE Alcantara</b>
First Registrationdate:	<b>3/07/2013</b>	Fiscalpower:	<b>149PK</b>
Expertise Mileage:	<b>159656</b>	Power Kw:	<b>110</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3105</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather and alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/101 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>BF Goodrich: 4 mm</b>	Fr.R.	<b>BF Goodrich: 4 mm</b>
	Re.L.	<b>BF Goodrich: 5 mm</b>	Re.R.	<b>BF Goodrich: 5 mm</b>





















**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1426,61
Windscreen, Stone chip(s), E - Replace	0,00



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R R, Scratch(es), Smart repair	110,64

		Wing R R, Bump(s) and scratch(es), Acceptable	0,00		
<i>No pictures to display</i>					
		Trunk lid covering R, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>					
		Seat cover R L, Dirty, Cleaning	25,00		
		Rearview mirror housing L, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>					
		Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16		
			Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09	
		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00	
			Bumper corner R L, Scratch(es), Smart repair		110,64
		Door trim F R, Scratch(es), Smart repair		110,64	
			Alloy rim R L, Damaged, E - Replace		277,44
			Backrest cover R M, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>					
		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00		

