


**PEUGEOT 508: 1GKS878**

Vinnumber:	<b>VF38E9HD8EL007218</b>	Versionname:	<b>508 SW e-HDi Active STT</b>
First Registrationdate:	<b>5/03/2014</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>128903</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Break</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2120</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Panoramic roof
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Head-up Display		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**


Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1018,50</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>


**Seat cover F L, Stain, Cleaning**
**25,00**



Wing R L, Scratch(es), LI - Repair and paint (complete) 0,00




Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35




Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Roof pillar L, Bump(s), Acceptable 0,00

No pictures to display

Roof, Hail damage, PDR - Hail 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display


Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover F R, Stain, Cleaning 25,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Seat cover R, Stain, Cleaning 25,00

