



**RENAULT Kangoo: 1ENU570**

Vinnumber:	<b>VF1KW24B548563123</b>	Versionname:	<b>KANGOO Authentique FAP 75PK</b>
First Registrationdate:	<b>1/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>117015</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2233</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1083,00
Wheel cover F R, Scratch(es), E - Replace	22,50



Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Bonnet, Bad repair, Paint	0,00
---------------------------	------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	361,13
---	--------



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------

