



VOLKSWAGEN Passat: 1FKA652

Vinnnumber:	WVWZZ3CZEE030320	Versionname:	PASSAT VAR Trendline BM 105PK
First Registrationdate:	23/07/2013	Fiscalpower:	
Expertise Mileage:	129363	Power Kw:	77
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3832
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2397,18
-------------------	---------

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Interior, Dirty, Chemical cleaning	150,00
------------------------------------	--------





Bumper cover R M, Broken, E - Replace 149,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display


Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Ceiling, Tear, E - Replace 494,00



Wheel cover F R, Scratch(es), E - Replace 30,00




Interior, Smell, Ozone treatment 152,58

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Full screen GPS, Scratch(es), E - Replace 998,00

