



## VOLKSWAGEN Caddy: 1DPL120

Vinnnumber:	<b>WV2ZZZ2KZCX155829</b>	Versionname:	<b>CADDY LIFE Baseline 75PK</b>
First Registrationdate:	<b>13/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>247825</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3225</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining artificial leather</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>NOT OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	328,33
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror basis L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), 67 - Polish	55,19
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	100,00



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Engine protective plate, Hole, E - Replace	40,00



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace 22,50



Door panel F R, Scratch(es), Smart repair 110,64

