



**VOLKSWAGEN GOLF VARIANT: 1SNA287**

Vinnnumber:	<b>WVWZZZAUZHP756379</b>	Versionname:	<b>1.6 TDi 85kW Comfortline</b>
First Registrationdate:	<b>12/06/2017</b>	Fiscalpower:	<b>DSG</b>
Expertise Mileage:	<b>21941</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3106</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
Adaptive cruise control	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>225/45/17/91 H LightMetal</b>			
	Fr.L.	<b>Michelin: 7,5 mm</b>	Fr.R.	<b>Michelin: 7,5 mm</b>
	Re.L.	<b>Michelin: 7,5 mm</b>	Re.R.	<b>Michelin: 7,5 mm</b>

**Assistance equipment**

Total cost ex VAT	838,20
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), E - Replace	487,20
--	--------




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s), PDR - Knock out without painting 111,00



Interior, Dirty, Chemical cleaning 50,00

