


BMW 3: 1GDP992

Vinnumber:	WBA3D11010J625858	Versionname:	3 BER 318d 136PK
First Registrationdate:	9/01/2014	Fiscalpower:	
Expertise Mileage:	25830	Power Kw:	100
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4433
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment



Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3496,39
-------------------	---------

Wing F L, Chemical polution, LI - Repair and paint (complete)	220,18
---	--------



Tailgate, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35




Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Chemical polution, LI - Repair and paint (complete) 318,35



Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Door F R, Chemical polution, LI - Repair and paint (complete) 318,35



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 50,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Chemical polution, LI - Repair and paint (complete)

220,18



Wing R L, Chemical polution, LI - Repair and paint (complete)

356,20

