



BMW 3: 1GQI759

Vinnnumber:	WBA3K11020F831859	Versionname:	3 TOURING 318d 143PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	161426	Power Kw:	105
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Total cost ex VAT	120,00
Alloy rim F L, Damaged, LI - Repair and paint (complete)	95,00



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display	
Seat cover F.R. Stain, Cleaning	25,00

Seat Cover / N, stain, cleaning	20,00
---------------------------------	-------



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

No pictures to display