


BMW 3: 1GMI618

Vinnumber:	WBA3Y11010D448960	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	11/03/2014	Fiscalpower:	
Expertise Mileage:	91752	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 27000 KM	Parking lot:	3412
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunction		Rear parking sensors	
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/18/99 V LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		74,00
Alloy rim F R polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L polished, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L polished, Scratch(es), Acceptable		0,00

<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	74,00

