



**BMW 3: 1GK135**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WBA3Y11000D448982</b> | Versionname: | <b>3 GRAN TURISMO 318d</b> |
| First Registrationdate:            | <b>3/03/2014</b>         | Fiscalpower: | <b>143PK</b>               |
| Expertise Mileage:                 | <b>99796</b>             | Power Kw:    | <b>105</b>                 |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Silver</b>              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Maintenance:                       | <b>BINNEN 5000 KM</b>    | Parking lot: | <b>3327</b>                |
| Battery functioning:               | <b>Yes</b>               |              |                            |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |
| GPS storage                    |                              | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Seats F heated                 |                              |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining leather</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/97 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Pirelli: 5 mm</b>     | Fr.R. | <b>Pirelli: 5 mm</b>     |
|               | Re.L.                            | <b>Bridgestone: 7 mm</b> | Re.R. | <b>Bridgestone: 7 mm</b> |

**Assistance equipment**

|  |         |                |
|--|---------|----------------|
|  | Runflat | <b>Yes</b>     |
| Total cost ex VAT  |         | <b>1174,35</b> |
| Side window trim R L, Bump(s) and scratch(es), E - Replace |         | <b>50,00</b>   |



|   |  |             |
|---|--|-------------|
| Ignition key, Not functioning (well), P - Check |  | <b>0,00</b> |
|---|--|-------------|



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 404,20



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), LI - Repair and paint (complete) 0,00

