



BMW 3: 1GKS889			
Vinnumber:	WBA3D31020J307680	Versionname:	3 BER 320d 184PK
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	130163	Power Kw:	135
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2703
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/45/18/95 V LightMetal			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	525,80
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
------------------------------------------------------------------------------	--------------



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting 63,00



Tailgate, Bump(s), PDR - Knock out without painting 82,80

