


BMW 1: NF6878

Vinnumber:	WBA1C31070P544740	Versionname:	1 BER HATCH 120d 184PK
First Registrationdate:	30/06/2014	Fiscalpower:	
Expertise Mileage:	133520	Power Kw:	135
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3728
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	DVD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/15/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

 Runflat **Yes**


 Total cost ex VAT **700,40**

 Door F R, Bump(s), PDR - Knock out without painting **63,00**

 Roof pillar R, Bump(s), PDR - Knock out without painting **63,00**



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 80,00



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Door seal F L, Damaged, E - Replace 54,00



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Door R L, Bump(s), PDR - Knock out without painting 82,80



Door F L, Bump(s), PDR - Knock out without painting 82,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display