


FORD C-MAX: 1FPE649

Vinnumber:	WF0JXXWPBJDG16838	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	12/09/2013	Fiscalpower:	
Expertise Mileage:	109461	Power Kw:	70
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3501
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1141,24
-------------------	----------------

Door panel R L, Scratch(es), E - Replace	114,00
--	---------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Seat cover F R, Stain, Cleaning 25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Stain, Cleaning 25,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

