



CITROEN C5: 1EPB434

Vinnnumber:	VF7RD9HD8CL538527	Versionname:	C5 BER e-HDi Bus.GPS Plus
First Registrationdate:	12/02/2013	Fiscalpower:	BMP 113PK Aut.
Expertise Mileage:	145427	Power Kw:	84
Bodytype:	Berline	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4405
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	HD
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/102 H LightMetal			
Winter tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Other: 8,5 mm	Re.R.	Other: 8,5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	301,68
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Bad repair, Paint	0,00



Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), P - Check 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Front bumper, Bad repair, Paint 0,00



Steering wheel, Worn, Acceptable 0,00



Seat cover F L, Worn, Acceptable 0,00

