



AUDI A3: 1EFQ424			
Vinnumber:	WAUZZZ8P8DA043307	Versionname:	A3 SB Attraction Start/Stop DPF 136PK
First Registrationdate:	19/11/2012	Fiscalpower:	
Expertise Mileage:	145035	Power Kw:	100
Bodytype:		Body color:	Anthracite
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1046,98
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Maintenance book, Missing, P - Check 0,00

No pictures to display

Alloy rim F L, Damaged, Acceptable 0,00

No pictures to display

Alloy rim F R, Damaged, LI - Repair and paint (complete) 95,00



Seat cover R L, Stain, Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00



Door frame F L, Damaged, Acceptable 0,00

No pictures to display

Wing F L, Bump(s), LI - Repair and paint (complete) 220,18



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Armrest F Mid, Broken, Acceptable 0,00

