



DACIA Lodgy: 1RFC524			
Vinnumber:	UU1JSDBC647945713	Versionname:	LODGY LauREATE 7pl. 107PK
First Registrationdate:	6/11/2012	Fiscalpower:	
Expertise Mileage:	77754	Power Kw:	79
Bodytype:	MPV	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2210
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Rear parking sensors
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

















Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1045,90
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear window, Scratch(es), E - Replace			320,00



Door F.R. Bump(s), RDP - Knock out without painting			63,00
---	--	--	--------------

		Door L, Bump(s), FDR - Knock out without painting	65,00
		Front bumper, Incomplete, E - Replace	49,00
		Wing R R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display		Tailgate, Scratch(es), LI - Repair and paint (complete)	241,34
		Wheel cover F L, Scratch(es), E - Replace	24,00
		Wheel cover F R, Scratch(es), E - Replace	24,00
		Wing R L, Chemical pollution, LI - Repair and paint (complete)	246,56
		Wheel cover R L, Scratch(es), E - Replace	24,00
		Bumper grille, Broken, E - Replace	54,00
		Bumper R, Scratch(es), Acceptable	0,00
No pictures to display		Front bumper, Scratch(es), Acceptable	0,00
No pictures to display			