



FORD TOURNEO CONNECT: 1STN712

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnnumber: | WFOUXXWPGUHR67077 | Versionname: | |
| First Registrationdate: | 12/07/2017 | Fiscalpower: | |
| Expertise Mileage: | 6915 | Power Kw: | 88 |
| Bodytype: | MPV | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4615 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/60/16/96 V LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 7 mm | Fr.R. | Continental: 7 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

Assistance equipment

| | |
|----------------------------------|--------|
| Total cost ex VAT | 217,56 |
| Bumper R, Bad repair, Acceptable | 0,00 |



| | |
|--------------------------------------|------|
| Tailgate handle, Damaged, Acceptable | 0,00 |
|--------------------------------------|------|



| | |
|---|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 217,56 |
|---|--------|

