


AUDI A4: 1GNZ180

| | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8K1EN035628 | Versionname: | A4 BER 120PK |
| First Registrationdate: | 21/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 58280 | Power Kw: | 88 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1508 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|-------------------------|------------------------------|------------------|
| Radio CD | | Central consol F |
| GPS storage | DVD | |
| GPS storage | | |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/16/95 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|----------------|
| Total cost ex VAT | 1683,03 |
|-------------------|----------------|

| | |
|-----------------------------------|-------------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|






No pictures to display

| | |
|---|---------------|
| Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|---------------|



| | |
|--------------------------------------|-------------|
| Rear window, Scratch(es), Acceptable | 0,00 |
|--------------------------------------|-------------|

No pictures to display

| | |
|--|--------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Chemical polution, LI - Repair and paint (complete) | 211,80 |
|  | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|  | |
| Roof, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Bump(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|  | |
| Roof, Chemical polution, LI - Repair and paint (complete) | 481,50 |
|  | |
| Wing F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 268,18 |
|  | |
| Bonnet, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |