

AUDI A4: 1GRJ632			
Vinnumber:	<b>WAUZZZ8K2EA136247</b>	Versionname:	<b>A4 AVANT TDi 120PK</b>
First Registrationdate:	<b>8/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>195731</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4223</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	DVD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	


Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Winter tyres:	<b>245/40/18/97 V LightMetal</b>			
	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6,5 mm</b>	Re.R.	<b>Michelin: 6,5 mm</b>

Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>619,88</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Interior, Dirty, Cleaning			<b>100,00</b>
---------------------------	--	--	---------------



Roof, Chemical pollution, LI - Repair and paint (complete) 0,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Backrest cover R L, Scratch(es), Smart repair 64,32



Bumper F R, Scratch(es), It - Spot repair 115,56



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Interior, Smell, Ozone treatment 0,00

