



**AUDI A3: 1GNP811**

Vinnnumber:	<b>WAUZZZ8V5EA143901</b>	Versionname:	<b>A3 SB Ambition S-tr.150PK Aut.</b>
First Registrationdate:	<b>19/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>165123</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1505</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 7,5 mm</b>	Fr.R.	<b>Dunlop: 7,5 mm</b>
	Re.L.	<b>Dunlop: 8 mm</b>	Re.R.	<b>Dunlop: 8 mm</b>


**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>807,26</b>
Door F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Rocker panel inner F R, Bump(s), PDR - Knock out without painting	<b>48,00</b>



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>
---	---------------



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bad repair, Paint 0,00



Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door panel R L, Stain, Cleaning 25,00



Wing F R, Repaired, Acceptable 0,00

No pictures to display