



<b>MINI Mini: 1EMA918</b>			
Vinnumber:	<b>WMWSW11070T463339</b>	Versionname:	<b>MINI One D 90PK DPF</b>
First Registrationdate:	<b>18/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>50951</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3827</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>175/65/15/84 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>763,19</b>
Bonnet, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing moulding F R, Scratch(es), Smart repair			<b>110,64</b>




Sunblind L, Damaged, E - Replace			<b>150,00</b>
----------------------------------	--	--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Reflector, Broken, E - Replace

95,00




Wing R R, Bump(s), Acceptable

0,00

No pictures to display

Rear spoiler, Chemical pollution, LI - Repair and paint (complete)

115,56



Rearview mirror housing L, Scratch(es), 67 - Polish

55,19



Seat cover F L, Stain, Cleaning

25,00



Windscreen, Repaired, Acceptable

0,00

No pictures to display