



MERCEDES GLK: 1CKV946

Vinnnumber:	WDC2049841F838698	Versionname:	GLK 220 CDI BE 4M St/St 163PK Aut.
First Registrationdate:	21/12/2011	Fiscalpower:	
Expertise Mileage:	88928	Power Kw:	120
Bodytype:	SUV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1425
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Type of headlighting: Headlighting Halogen	Rear parking sensors
Type of GPS: GPS big screen color	
Type of Lining: Lining fabrics	
Type of climate control: Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	235/60/17/102 H LightMetal			
Winter tyres:	Fr.L.	Continental: 8 mm	Fr.R.	Continental: 8 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1345,28
-------------------	---------

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Interior, Dirty, Cleaning	50,00
---------------------------	-------



Trunk lid covering R, Bump(s), Smart repair 110,64



Windscreen, Damaged, E - Replace 560,64



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84

