


**FORD Fiesta: 1HFB572**

Vinnumber:	<b>WF0RXXGAKREU01861</b>	Versionname:	<b>FIESTA VAN Ambiente</b>
First Registrationdate:	<b>4/07/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>278254</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4406</b>
Number of doors:	<b>3</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Windows electric F	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/50/15/82 H Steel</b>			
Winter tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>478,44</b>
-------------------	---------------

Wheel cover F L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Tailgate, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Bonnet, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------	-------------

*No pictures to display*

Wheel cover R R, Missing, E - Replace	<b>24,00</b>
---------------------------------------	--------------

*No pictures to display*

Wheel cover R L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Strained , P - Check 0,00



Interior, Dirty, Acceptable 0,00



Door F L, Bump(s), PDR - Knock out without painting 63,00



Ignition key, Missing, E - Replace 150,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display