



FORD Kuga: 1EZL391

Vinnnumber:	WF0AXXWPMADM26332	Versionname:	KUGA 2WD Trend 136PK
First Registrationdate:	29/04/2013	Fiscalpower:	
Expertise Mileage:	134399	Power Kw:	100
Bodytype:	SUV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4403
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Sun Roof electric
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/103 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	423,80
Wing R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Spoiler R, Deformed, E - Replace	59,00



Wing moulding F R, Scratch(es), Smart repair	110,64
--	--------



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16

