


MERCEDES A: 1GUK361

Vinnumber:	WDD1760111V016139	Versionname:	A 160 CDI 90PK
First Registrationdate:	5/05/2014	Fiscalpower:	
Expertise Mileage:	81523	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2820
Maintenance:	27/04/2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			210,56
Wing F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear window, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Roof, Stone chip(s), Acceptable

0,00

No pictures to display

Alloy Rims (all), Rust, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display