



MERCEDES C 220 CDI: 1FRV242

Vinnumber:	WDD2042021G195114	Versionname:	C BRE 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	4/10/2013	Fiscalpower:	
Expertise Mileage:	146451	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3103
Maintenance:	SERVICE B5 IN 70D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	581,60
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Interior, Worn, Acceptable	0,00
----------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Gear shift lever knob, Worn, Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00

