


MERCEDES B: 1EKN217

Vinnumber:	WDD2462001J136721	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	7/01/2013	Fiscalpower:	
Expertise Mileage:	145085	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2227
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	481,16
-------------------	--------

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
---	--------





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Windscreen, Stone chip(s), Windscreen repair 58,80

