


MERCEDES A: 1GDZ645

Vinnumber:	WDD1760121J234527	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	13/01/2014	Fiscalpower:	
Expertise Mileage:	42585	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4205
Maintenance:	B5 19 DAGEN OVERSCHREDEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Kumho: 6 mm	Fr.R.	Kumho: 6 mm
	Re.L.	Kumho: 7 mm	Re.R.	Kumho: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT	836,15		
Wing R L, Bump(s) and scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Wheel cover F L, Scratch(es), Acceptable	0,00		
<i>No pictures to display</i>			
Wheel cover R L, Scratch(es), E - Replace	30,00		





Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 366,35



Wheel cover F R, Scratch(es), E - Replace 30,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 259,80



Maintenance, Maintenance, Execute 0,00



Ignition key, Missing, E - Replace 150,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display