



MERCEDES E: 1GMQ945

Vinnnumber:	WDD2122821A983538	Versionname:	E BRE 250CDI 4Matic BE 204PK Aut.
First Registrationdate:	12/03/2014	Fiscalpower:	
Expertise Mileage:	166922	Power Kw:	150
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3115
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Seats F L ventilated
Windows electric F		Seats F R ventilated
Windows electric R		Sun Roof electric
Cruise Control		Central consol F
Steering wheel multifunctional		Luggage cover
Seats F heated		Front parking sensors
Type of headlighting	Headlighting Xenon	Rear parking sensors
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/99 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 8 mm	Fr.R.	Pirelli: 8 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	832,16
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror R complete, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00





Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16

