



|                                  |                                 |              |   |
|----------------------------------|---------------------------------|--------------|---|
| <b>OPEL Vivaro 2700: 1DVL998</b> |                                 |              |   |
| Vinnnumber:                      | <b>WOLF7A1ASCV628819</b>        | Versionname: | <b>VIVARO 2700 B/F SWB L1H1(EU5)115PK</b> |
| First Registrationdate:          | <b>10/09/2012</b>               | Fiscalpower: |   |
| Expertise Mileage:               | <b>96011</b>                    | Power Kw:    | <b>84</b>                                 |
| Bodytype:                        | <b>Transporter</b>              | Body color:  | <b>Light Grey</b>                         |
| Gearbox:                         | <b>MAN 6 VIT</b>                | Paint type:  | <b>Metalic</b>                            |
| Transmission:                    |                                 | Rims summer: | <b>Steel</b>                              |
| Fueltype:                        | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                 |
| Battery functioning:             | <b>Yes</b>                      | Parking lot: | <b>TRU17</b>                              |
| Number of doors:                 | <b>5</b>                        |              |   |
| Number of seats:                 | <b>3</b>                        |              |   |
| Number head rests:               | <b>3</b>                        |              |   |
| Rims summer:                     | <b>Steel</b>                    |              |   |
| Category:                        | <b>Light Commercial Vehicle</b> |              |   |
| Oil level:                       | <b>OK</b>                       |              |   |

|                          |                               |
|--------------------------|-------------------------------|
| <b>Options</b>           |                               |
| Windows electric F       | Rear parking sensors          |
| Type of headlighting:    | <b>Headlighting Halogen</b>   |
| Type of Lining:          | <b>Lining fabrics</b>         |
| Type of climate control: | <b>Manual climate control</b> |


|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                              |                          |       |                          |
|-----------------------|------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                              |                          |       |                          |
|                       | <b>205/65/16/107 T Steel</b> |                          |       |                          |
| Winter tyres:         | Fr.L.                        | <b>Bridgestone: 7 mm</b> | Fr.R. | <b>Bridgestone: 7 mm</b> |
|                       | Re.L.                        | <b>Bridgestone: 9 mm</b> | Re.R. | <b>Bridgestone: 9 mm</b> |

|                             |            |
|-----------------------------|------------|
| <b>Assistance equipment</b> |            |
| Spare wheel                 | <b>Yes</b> |

|                                  |        |
|----------------------------------|--------|
| Total cost ex VAT                | 500,68 |
| Seat cover F L, Worn, Acceptable | 0,00   |

|                                      |       |
|--------------------------------------|-------|
| <i>No pictures to display</i>        |       |
| Rear wiper arm, Missing, E - Replace | 74,00 |



|   |        |
|---|--------|
| Trunk door R R, Bump(s), It - Spot repair | 115,56 |
|---|--------|





|  |        |
|--|--------|
| Roof pillar L, Bump(s) and scratch(es), It - Spot repair | 115,56 |
|--|--------|



|                           |       |
|---------------------------|-------|
| Interior, Dirty, Cleaning | 50,00 |
|---------------------------|-------|



|                                   |      |
|-----------------------------------|------|
| Wing F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|  |       |
|--|-------|
| Rear wiper blade, Missing, E - Replace | 30,00 |
|--|-------|

*No pictures to display*

|   |        |
|---|--------|
| Trunk door R L, Bump(s), It - Spot repair | 115,56 |
|---|--------|



|   |      |
|---|------|
| Rocker panel inner F L, Bump(s), Acceptable | 0,00 |
|---|------|

*No pictures to display*

|                               |      |
|-------------------------------|------|
| Door R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

*No pictures to display*