


RENAULT Kangoo: 1GNF709

Vinnumber:	VF1KWX8B550517573	Versionname:	KANGOO Energy Intens
First Registrationdate:	17/03/2014	Fiscalpower:	90PK
Expertise Mileage:	83647	Power Kw:	66
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2704
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	717,76
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---------------------------------------------------------------------	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable	0,00
-----------------------------------------------	------

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
-------------------------------------------------------------	--------



Sill outer R, Bump(s), PDR - Knock out without painting 63,00



Roof, Bad repair, Paint 0,00



Door F R, Bump(s), PDR - Knock out without painting 63,00

