




PEUGEOT 5008: 1EWM317			
Vinnnumber:	VF30A9HD8DS058833	Versionname:	5008 Allure FAP 115PK
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	173827	Power Kw:	84
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar fixed
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/50/17/95 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Total cost ex VAT	2006,35
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------





Steering wheel, Missing, E - Replace

98,00



Front bumper, Damaged, Le - Replace and paint

735,00



Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

50,00



