


**RENAULT Clio: 1GJA307**

Vinnnumber:	<b>VF17R040H50102991</b>	Versionname:	<b>CLIO IV BRE Expression</b>
First Registrationdate:	<b>20/02/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>127588</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4227</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1421,80</b>
Front bumper, Stone chip(s), Acceptable	<b>0,00</b>

*No pictures to display*


Tailgate, Scratch(es), LI - Repair and paint (complete)	<b>241,34</b>
---	---------------



Wheel cover F R, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Roof, Chemical pollution, LI - Repair and paint (complete) 385,20



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 96,00



Door moulding Lower F R, Scratch(es), E - Replace 96,00



Wheel cover R R, Scratch(es), E - Replace 24,00



Interior, Dirty, Cleaning 25,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)

304,06



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display