



PEUGEOT 508: 1ELS638			
Vinnumber:	VF38E9HLOCL088259	Versionname:	508 SW Style 115PK
First Registrationdate:	16/01/2013	Fiscalpower:	
Expertise Mileage:	139194	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4604
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/55/16/98 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	653,35
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Protection plate M, Broken, E - Replace 0,00



Front bumper, Damaged, Le - Replace and paint 0,00




Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Damaged, Le - Replace and paint 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper grille, Damaged, E - Replace 0,00



Interior, Dirty, Cleaning 50,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display